










3 DELOITTE WAY

- floor plans
- roof plan
- section
- elevations
- renderings













photovoltaic panels*



*Quantity of photovoltaic panels is to be determined based on required output to achieve LEED









*New proposed material; compatible with DU1





*New proposed material; compatible with DU1

NE Building | Typical Guestroom Exterior Finishes - All Materials Match DU1 Unless Noted




01 Standing Seam Metal-Factory Applied Paint to Match DU1




02 Exterior Hardiplank Wood Siding - Painted to Match DU1




03 Exterior EIFS with Joint Pattern



05 Metal Fin Frame at Guestroom Windows & Mullions



09.2 Typ. Guestroom Window Glass
Solarban 90 coating on Acuity glass
Color: Transparent with Low reflectivity
U Value: 0.29



*New proposed material; compatible with DU1


NE Building | Typical Classroom Exterior Finishes - All Materials Match DU1 Unless Noted




04 Texas Limestone Veneer with Mortar Joints



08 Delta Millworks, Shou Sugi Ban, Charred Wood*




06 Metal Fin Frame & Metal Panel - Blackened Steel Finish*



05 Metal Soffit




10 Cable & Steel Guard-rail



07 Wood Siding*




09.1 Curtain Wall Glass
Solarban 72 coating on Acuity glass
Color: Transparent with Low reflectivity
U Value: 0.29



*New proposed material; compatible with DU1




09.1 Curtain Wall Glass
Solarban 72 coating on Acuity glass
Color: Transparent with Low reflectivity
U Value: 0.29




05 Typ. Curtain Wall Mullion & Metal Panel Profile




02 Exterior Hardiplank Wood Siding - Painted to Match DU1



01 Standing Seam Metal-Factory Applied Paint to Match DU1




*New proposed material; compatible with DU1





01 Standing Seam Metal-Factory Applied Paint to Match DU1



09.2 Curtain Wall Glass
Solarban 90 coating on Acuity glass
Color: Transparent with Low reflectivity
U-Value: 0.29



05 Typ. Curtain Wall Mullion




*New proposed material; compatible with DU1

North East Building		
Total Exterior Walls *	124,428 *	100% *
Masonry		41%
Wood Appearance		21%
Metal Frame		1%
Glazing		36%
Trim		0%
Standing Seam Metal Panel		1%

*SF and percentage totals include the primary, exposed building exterior wall materials (e.g., Masonry, Wood Appearance, Glazing). Building roof, walking surfaces, landscaped areas, railings and architectural screening elements are excluded. Doors are calculated within the primary wall material SF and percentage (e.g., Masonry, Wood Appearance, Glazing). Punched windows are included within the Glazing areas.

EIFS Benefits Over Stucco:

- Significantly Less Cracking Potential
- Better Long Term Operations & Maintenance Attributes
- Enhanced Thermal Performance
- Greater Fade Resistance from Long Term UV Exposure
- Improved Acoustic Performance
- More Sustainability Benefits – Lower Carbon Footprint
- Offsite Prefabrication Potential for Higher Craftsmanship
- To be implemented as a Modern Drainable, Continuously Insulated, System




01 Standing Seam Metal




02 Wood Appearance (Exterior Hardie Plank)




03 Masonry (Exterior EIFS)



04 Masonry (Texas Limestone Veneer)



05 Metal Frame & Trim



07 Wood Appearance (Wood Siding)



08 Wood Appearance (Charred Wood)



09 Glazing

